


CM-s

MEASUREMENT CONVERTER LOW COST

DIMENSIONS



JUNCTIONS

TERMINAL	DESCRIPTION
A	Supply 24Vdc or 48Vdc
B	Supply 0V
C	Output O+
D	Output O-
E	N.A.
F	N.A.
G	Input I-
H	Input I+